NON-CORE ISSUES

Facility	License #	Physical Address	Phone Number
Bridgeview Estates - RCF	RC-404	1828 Bridgeview Boulevard	208-736-3933
Administrator	City	Zip Code	Survey Date
Katherine Aleman	Twin Falls	83301	03/26/2024
Survey Team Leader	Survey Type		Response Due
Chaney, Linda	Fire Life Safety and Sanitation Licensure		04/25/2024

Item #	Rule (16.03.22)	Description
1	.405.03. Telephone.	1.) Observation during the facility tour revealed an unsecured oxygen cylinder in resident room #514.(NFPA 99, 11.6.2.3) - 2.) Observation during the facility tour revealed the oxygen transfilling room was equipped with one exhaust fan located in the ceiling of the room. There was no inlet for the mechanical exhaust system located one foot from the floor and adjacent to the cylinders.(NFPA 99, 9.3.6.5.3.3)
2	.404. FIRE AND LIFE SAFETY STANDARDS FOR EXISTING BUILDINGS LICENSED FOR SEVENTEEN OR MORE RESIDENTS AND MULTI-STORY BUILDINGS.	The facility did not maintain compliance with the 2018 edition of NFPA 101, Life Safety Code, Chapter 33, Existing Residential Board and Care Occupancies, Large Facilities as evidenced by the following: 1.) The annual fire alarm inspection did not identify the location of all devices tested, to include notification devices (horn/strobes) and magnetic hold open devices interconnected to the fire alarm system.(NFPA 72, 14.6.2.4)