NON-CORE ISSUES

Facility	License #	Physical Address	Phone Number
Bridgeview Estates - RCF	RC-404	1828 Bridgeview Boulevard	208-736-3933
Administrator	City	Zip Code	Survey Date
Scott Morehouse	Twin Falls	83301	03/11/2025
Survey Team Leader	Survey Type		Response Due
Burbank, Sam	Fire Life Safety and Sanitation Licensure		04/10/2025

Item #	Rule (16.03.22)	Description
1	.404. FIRE AND LIFE SAFETY STANDARDS FOR EXISTING BUILDINGS LICENSED FOR SEVENTEEN OR MORE RESIDENTS AND MULTI-STORY BUILDINGS.	1) Facility failed to ensure fire barriers for separation of occupancy would fully self-close and latch in accordance with NFPA 101, Chapter 33: Two-hour fire barrier at the lobby and the two-hour fire barrier at the south side separating to the corridor abutting the SNF, would not fully close and latch. 2) Fire suppression system pendants shall not show signs of loading, corrosion or non-factory applied paint in accordance with NFPA 25: Fire suppression system pendant above the washers of the laundry was found to be loaded with lint. All pendants identified with this condition shall be replaced. 3) Medical records storage is approximately 80 square feet in size and determined classified as a hazardous area. Door to the space was not equipped to self-close in accordance with NFPA 101, Chapter 33.
2	.405.02.a. Prohibited Applications.	Relocatable power taps are prohibited with the use of medical devices: Resident rooms 508 and 519 both were using a RPT to supply power to an oxygen concentrator.
3	.405.03. Telephone.	Medical gas cylinders shall be secured to prevent damages to cylinders in accordance with NFPA 99, Chapter 11: 46 liter liquid oxygen liberator in the oxygen transfill room was not secured by either a chain or a rack.