NON-CORE ISSUES

Facility	License #	Physical Address	Phone Number
Midland Manor	RC-854	9 South Midland Boulevard	208-466-5175
Administrator	City	Zip Code	Survey Date
Miranda Peters	Nampa	83651	02/23/2024
Survey Team Leader	Survey Type		Response Due
Wilson, Jeremy	Fire Life Safety and Sanitation Licensure		03/24/2024

Item #	Rule (16.03.22)	Description
8	.403. FIRE AND LIFE SAFETY STANDARDS FOR EXISTING BUILDINGS LICENSED FOR THREE THROUGH SIXTEEN RESIDENTS.	No documented sensitivity testing completed for smoke detectors. Seven (7) smoke detectors were replaced/ newly installed in 2019 and have not been tested in accordance with NFPA 72, Chapter 14, Section 14.4.4.3.1-14.4.4.3.3. Last documented sensitivity test was dated 2/8/2019. REPEAT Previously cited 1/21/22. 14.4.4.3.1 Sensitivity shall be checked within 1 year after installation. 14.4.4.3.2 Sensitivity shall be checked every alternate year thereafter unless otherwise permitted by compliance with 14.4.4.3.3. 14.4.4.3.3 After the second required calibration test, if sensitivity tests indicate that the device has remained within its listed and marked sensitivity range (or 4 percent obscuration light gray smoke, if not marked), the length of time between calibration tests shall be permitted to be extended to a maximum of 5 years.

9	.405.04. Prohibited Applications.	Fuel-fired heating devices and systems must be inspected, serviced, and cleaned at least annually by a person professionally engaged in the business of servicing these devices or systems.