NON-CORE ISSUES

Facility	License #	Physical Address	Phone Number
Creekside Inn Assisted Living Alzheimer's Community	RC-954	240 East Kathleen Avenue	208-665-2444
Administrator	City	Zip Code	Survey Date
Bennett Kirk Goodin	Coeur d'Alene	83815	03/25/2022
Survey Team Leader	Survey Type		Response Due
Chaney, Linda	Fire Life Safety and Sanitation Licensure		04/24/2022

Item #	Rule (16.03.22)	Description
1	.250.10.d. Heating, Ventilation, and Air-Conditioning (HVAC).	Fire and smoke dampers must be inspected, serviced, and cleaned once every four (4) years by a person professionally engaged in the business of servicing these devices or systems. A copy of these results must be kept in the facility. No documentation could be provided at the time of survey for the testing of installed fusible-linked fire dampers. Dampers were observed during the facility tour in both the laundry and kitchen.