NON-CORE ISSUES

Facility	License #	Physical Address	Phone Number
Bridgeview Estates - RCF	RC-404	1828 Bridgeview Boulevard	208-736-3933
Administrator	City	Zip Code	Survey Date
Katherine Aleman	Twin Falls	83301	01/04/2023
Survey Team Leader	Survey Type		Response Due
Burbank, Sam	Fire Life Safety and Sanitation Licensure		02/03/2023

Item #	Rule (16.03.22)	Description
1	.404. FIRE AND LIFE SAFETY STANDARDS FOR EXISTING BUILDINGS LICENSED FOR SEVENTEEN OR MORE RESIDENTS AND MULTI-STORY BUILDINGS.	Facility smoke barrier doors shall fully self-close and resist the passage of smoke. Doors located at 5D would not fully self-close and left a gap of approximately 1-1/2 inches from each leading edge.
2	.405.01.a. Electrical Installations and Equipment.	Extension cords and multiple plug adapters are prohibited: Room 515 using a non-grounded extension cord. Corrected on site 1/4/23.
3	.405.03. Telephone.	No documented policies and procedures for the elimination of sources of ignition and misuse of flammable substances in accordance with NFPA 99, Chapter 11, Section 11.5.