NON-CORE ISSUES

Facility	License #	Physical Address	Phone Number
Apple Valley Residence	RC-1199	715 North Butte Avenue	208 365 1497
Administrator	City	Zip Code	Survey Date
Marilyn Godsill	Emmett	83617	01/24/2024
Survey Team Leader	Survey Type		Response Due
Wilson, Jeremy	Fire Life Safety and Sanitation Licensure		02/23/2024

Item #	Rule (16.03.22)	Description
1	.405.04. Prohibited Applications.	Facility could not provide annual inspection documentation on the date of the survey for the inspection of the facilities Fuel-Fired appliances or utilities. As required by this IDAPA rule.
2	.404. FIRE AND LIFE SAFETY STANDARDS FOR EXISTING BUILDINGS LICENSED FOR SEVENTEEN OR MORE RESIDENTS AND MULTI-STORY BUILDINGS.	Sprinkler heads in Kitchen X2, located in front of refrigerators, corroded and require replacement. Reference NFPA 25, Chapter 5, Section 5.2.1.1.1.
3	.155.01. Relocation Agreements.	Facility could not provide documentation of Relocation Agreements for what the facility termed as "Safe Houses" per facilities evacuation policy. As required by this IDAPA rule.