NON-CORE ISSUES

Facility	License #	Physical Address	Phone Number
Country Living Retirement of Mountain Home, Inc	RC-1122	1200 East 6th South	208-587-9073
Administrator	City	Zip Code	Survey Date
Tami Nichols	Mountain Home	83647	10/21/2024
Survey Team Leader	Survey Type		Response Due
Wilson, Jeremy	Fire Life Safety and Sanitation Licensure		11/20/2024

Item #	Rule (16.03.22)	Description
1	.404. FIRE AND LIFE SAFETY STANDARDS FOR EXISTING BUILDINGS LICENSED FOR SEVENTEEN OR MORE RESIDENTS AND MULTI-STORY BUILDINGS.	Facility failed to maintain UL listed hood ventilation systems in accordance with NFPA 96. During the facility tour of the commercial kitchen, it was identified the UL listed hood assemblies filtration panels had a gap of two inches on the left hand side of the assembly between the filter panels and the hood, further observation identified a 4-inch gap between the filter panels and the right hand side of the hood assembly, allowing grease laden vapors to bypass the filtration panels. Reference NFPA 96, Chapter 6, Section 6.2.3 Grease Filters. 6.2.3.1 Grease filters shall be listed. 6.2.3.2 Grease filters shall be constructed of noncombustible material. 6.2.3.3 Grease filters shall be of rigid construction that will not distort or crush under normal operation, handling, and cleaning conditions. 6.2.3.4 Grease filters shall be arranged so that all exhaust air passes through the grease filters.